



482735



482734

NEW!

REPLACEMENT TENSIONER SHOES



Replace the wear items only on 99-06 or 07-16 Twin Cam models.

Economical replacement for expensive factory H-D® parts, the Replacement Tensioner Shoes from Twin Power™ provide you with longer life and reduced friction. These shoes are high-temperature resistant. They allow you to replace only the worn items. Factory shoes should be checked every 10,000 miles. Made in USA.

Note: Installation tool P/N 482736 required for 99 – 06 models (except 06 Dyna).

HARLEY-DAVIDSON

P/N

99-06 Big Twin (Exc. Dyna)

482734

07-15 Big Twin, 2006 Dyna

482735

Learn more about [other motorcycle engine parts](#) by [Twin Power](#) on our website.