



## DUAL FUNCTION ANTENNA FOR TOUR PAK 865

FITS: '89 - UP H.D. TOUR- PAK MOUNT POSITION

### PARTS INCLUDED

- 1 Dual Function Antenna
- 1 Installation Instructions

Please read and understand entire instructions before starting installation.

### THANK YOU FOR CHOOSING KÜRYAKYN!

**IN ORDER TO PROTECT YOU AND OTHERS FROM POSSIBLE INJURY AND/OR PROPERTY DAMAGE OR LOSS, PLEASE PAY CLOSE ATTENTION TO ALL INSTRUCTIONS, WARNINGS, CAUTIONS AND ATTENTION NOTES REGARDING THE USE AND CARE OF THIS PRODUCT.**

**WARNING!** THIS INDICATION ALERTS YOU TO THE FACT THAT IGNORING THE CONTENTS DESCRIBED HEREIN CAN RESULT IN POTENTIAL DEATH OR SERIOUS INJURY.

**CAUTION!** This indication alerts you to the fact that ignoring the contents described herein can result in potential injury or material damage.

**ATTENTION!** This indication alerts you to the fact that ignoring the contents described herein may negatively affect product performance and functionality.

### TOOLS SUGGESTED

2.0 mm hex wrench

**STRICTLY OBSERVE THE FOLLOWING GUIDELINES IN ORDER TO USE THE PRODUCT PROPERLY AND AVOID POTENTIALLY DANGEROUS ACCIDENTS.**

### PROCEDURE

**STEP 1** Read and understand all steps in the instructions before starting the installation. Park the motorcycle on a hard, level surface and turn off the ignition.

**STEP 2** If applicable, loosen the setscrew at the base of the antenna.

**STEP 3** Turn the antenna counter clock wise to remove from the Tour Pak.

**STEP 4** Install the Dual Function Antenna in the reverse order the stock antenna was removed.

**STEP 5** Hold the antenna at the base when tightening, to ensure the threaded insert does not strip from the plastic housing.

**NOTE:** Do not fully remove the setscrew from the antenna.

**STEP 6** Be sure the antenna seats to the base of the stud then tighten the setscrew.

**ATTENTION!** It is the installer's responsibility to ensure that all of the fasteners (including pre-assembled) are tightened before operation of the motorcycle. Kuryakyn will not issue a warranty on components lost due to improper installation. Periodic maintenance may be required.

*Ride On!*