

READ AND UNDERSTAND THE SDS BEFORE USING THIS PRODUCT. (available at caliberproductsinc.com).

CAUTION: The surface must be clean, dry and free from all contaminants. Especially waxes, grease, oils or any residue. If any of these are present, thoroughly clean the surface first with LACQUER THINNER. If you do not do this, Alumi-Skin may have a streaky appearance, or may not adhere.

TO CLEAN: (New Aluminum) Thoroughly clean the surface with a mild soap and water solution to remove all contaminants, let dry then apply Alumi-Skin. (Oxidized Aluminum) Clean first with Alumi-Etch to remove streaks, stains and oxidation, dry, then apply Alumi-Skin.

TO APPLY: We recommend using a WHITE COTTON TOWEL/DIAPER ONLY! Look for the description "FLAT FOLD, BIRDSEYE WEAVE" on the packaging. These can be found at department stores and on line. For large areas, fold the cloth into a thick smooth pad about the size of your open hand. For smaller areas, cut the cloth down to an appropriate size. SATURATE the cloth by pouring Alumi-Skin directly from the container on to cloth. NEVER pour Alumi-Skin into a pan and dip cloth. A single swipe is all that's needed to apply a coat of Alumi-Skin. On larger areas, apply Alumi-Skin in sections. Moving from left to right, make a straight horizontal swipe (up to ten feet).

APPLICATION: Although Alumi-Skin can be applied in any temperature from 20°F to 100° F, the cooler the temperature the better the finish.

WARNING: FLAMMABLE. VAPOR HARMFUL. CAN CAUSE IRRITATION OF EYES, SKIN AND RESPIRATORY TRACT. Avoid contact with eyes and skin. Wear impervious clothing, footwear and equipment including gloves and splash-proof goggles to prevent eye and skin contact. Do not take internally. Avoid breathing of vapor or spray mist. Use paint spray mask and approved chemical-mechanical filter. In enclosed or confined areas use NIOSH/MSHA approved air respirators. Refer to OSHA Personal Protective Equipment Standards, 29 CFR 1910 Subpart I.

FIRE HAZARD: Keep away from heat, sparks and open flame. Do not smoke. Vapors may spread long distances and accumulate in low areas. Vapors may ignite. USE ONLY WITH ADEQUATE VENTILATION. Refer to OSHA regulations 29CFR 1910.94, 1910.107

FIRST AID PROCEDURES - SKIN CONTACT: Wipe area with clean cloth and wash thoroughly with soap and water. **EYE CONTACT:** Flush immediately and thoroughly with water for 15 minutes. Get medical attention. **INHALATION:** Move person to fresh air. Restore breathing. Get medical attention. **INGESTION:** Get medical attention immediately. **HANDLING & STORING:** Keep closures tight and upright to prevent leakage. Keep container closed when not in use. Store below 100 degrees F. Do not incinerate closed containers as they may explode when exposed to extreme heat or fire. Ground and bond drum when transferring product. **SPILLS AND LEAKS:** Absorb and dispose of in accordance with the local applicable regulations. Refer to OSHA storage requirements 29 CFR 1910.106

NOTICE: Chronic overexposure to solvents may cause permanent brain or nervous damage.



CAUTION – FLAMMABLE LIQUID
CONTAINS XYLENE, TOLUENE

Looking for dependable oils, fluids, lubricants? Rely on Caliber for quality and long-lasting products.