

Application Instructions

- 1. Make sure surface has been thoroughly cleaned and dried.
- 2. Focusing on a small section at a time, apply Metal Coat to an applicator and spread evenly across the metal surface, making sure to maintain even coverage.
- **3.** After fully covering that section use a clean, dry microfiber towel to remove excess product.
- **4.** Move on to the next section and repeat the process.

NOTE: Only apply to one section at a time. Wipe down immediately to avoid residue. Before applying, test a small amount in an inconspicuous place to check compatibility with surface.