



Sissybar


Suzuki VL1500 LC

Art.no. 523-1036A





Components 1 Side bracket 2x 2 Bolt M8 x 50 4x 3 Washer M8 4x



This accessory should be mounted by a professional mechanic only.

MotoLux International B.V. / Highway Hawk can not be held responsible for improper installation.

© Moto-Lux Specialties B.V. Barneveld - The Netherlands