



## **NEW PRODUCT RELEASE (No. 0233)**

**RE: DOT Turn Signals**

(1) Product Information:

<b><u>K&amp;S No.</u></b>	<b><u>Description</u></b>
<b>25-2341C</b>	KA # OEM 23040-0100, Front Right ZX-1000G Ninja 1000 (11-13), ZX-1000H Ninja 1000 ABS (12-16)
<b>25-2342C</b>	KA # OEM 23040-0099, Front Left ZX-1000G Ninja 1000 (11-13), ZX-1000H Ninja 1000 ABS (12-16)
<b>25-2351C</b>	KA # OEM 23040-0110, Front Right EX-650E Ninja 650 (12-16), EX-650F Ninja 650 ABS (13-16)
<b>25-2352C</b>	KA # OEM 23040-0109, Front Left EX-650E Ninja 650 (12-16), EX-650F Ninja 650 ABS (13-16)
<b>25-3281C</b>	SU # OEM 35601-41G00, Front Right GSX-R600 (06-16), GSX-R750 (06-16), GSX-R1000 (06-16)
<b>25-3282C</b>	SU # OEM 35602-41G00, Front Left GSX-R600 (06-16), GSX-R750 (06-16), GSX-R1000 (06-16)
<b>25-3303C</b>	SU # OEM 35603-47H00, Rear Right GSX-R600 (15-16), GSX-R750 (15-16), GSX-R750Z (14) GSX-R1000 (09, 11-16)
<b>25-3304C</b>	SU # OEM 35604-47H00, Rear Left GSX-R600 (15-16), GSX-R750 (15-16), GSX-R750Z (14) GSX-R1000 (09, 11-16)
<b>25-1321C</b>	HO # OEM 33403-MFL-671, <b>Front Right</b> VFR-800 F/FD (14-15), CBR-1000 RA/RR (08-16) CBR-1000 RS/S (14-15), VFR-1200 F/FD (10-14)
<b>25-1322C</b>	HO # OEM 33453-MFL-671, <b>Front Left</b> VFR-800 F/FD (14-15), CBR-1000 RA/RR (08-16) CBR-1000 RS/S (14-15), VFR-1200 F/FD (10-14)

# K&S TECHNOLOGIES, INC.

