



VStream® Windscreen
Installation and Owner's Manual
N20401, N20403, N20404,
N20405 and N20406
Harley-Davidson FLHTC/FLHX 1996~
Quantum™ coated polycarbonate

## Attention



Special notes and cautionary measures which can prevent damage to the accessory or motorcycle.

#### Note:



Tips for facilitation of operation, control and adjustment, as well as maintenance work.

## **TOOLS REQUIRED:**

T27 Torx Wrench

## PARTS LIST

Index Description

Qty.

Windshield, Quantum Hardcoated polycarbonate

1

reused.

REMOVAL AND RE-INSTALLATION
Retain all fasteners and parts as they will be

Avo insta

Avoid removing the center screw during installation if possible. It will make installaer

- **1.** Remove the left and right outside screws holding the stock windshield in place. **(T27 Torx Wrench)**
- 2. Loosen the center screw. (T27 Torx Wrench)
- 3. Remove stock windshield.
- 4. Install VStream windshield.
- 5. Tighten all screws. Do Not Overtighten.
- 6. Register your windshield. Refer to page 2.

## **MAINTENANCE**

**Cleaning:** Wash with a clean soft cloth, plenty of warm water and, if necessary, a non-abrasive soap such as dishwashing liquid. Flannel or soft chamois make good cleaning cloths. Do not use rain protective products on the screen due to the solvent action of the alcohol in these products. Do not allow brake fluid, alcohol, or strong solvents to contact the screen.

National Cycle Windshield Wash Part number N1401 is recommended for everyday cleaning. Product is supplied with a handy travel size container and rag for easy storage on the motorcycle.



National Cycle 3-Year Limited Warranty
Register your windshield on Line at: www.nationalcycle.com/register.html
or contact Customer Service at National Cycle, Inc. / PO Box 158 / Maywood, IL 60153 / USA
708/343/0400

National Cycle hereby warrants to the original registered owner of a National Cycle polycarbonate windshield for a period of three years from the date of purchase against breakage. This limited warranty is expressly limited to the replacement of the polycarbonate windscreen. This limited warranty does not include scratches, coating failure, cosmetic wear and tear, replacement of hardware, or any consequential damages or expenses including labor cost of installation, removal and/or replacement,

inconvenience, inbound freight expenses or damage to any other component of the motorcycle or any other accessories. Certain chemicals, generally known as acidic hydrocarbons, are known to cause polycarbonate damage and will not be covered under this limited warranty. Please refer to the cleaning instructions supplied with all National Cycle windshields.

# **A** WARNING

Never ride your motorcycle with loose accessory mounting hardware. Check the hardware for tightness regularly.

Today's motorcycles are built with enough frame rigidity to withstand the moderate loads imposed on them by the foreseeable addition of an accessory(ies). If an accessory(ies) adversely affects your motorcycle's stability, immediately remove the accessory(ies). Do not ride a motorcycle that exhibits unsafe handling traits.

Have experienced service personnel correct any problem before riding with the accessory(ies) installed. For further questions concerning handling problems associated with an accessory(ies), contact your dealer, motorcycle manufacturer, or accessory manufacturer.



N5200 Heat Deflector

Transparent dark tint Quantum<sup>™</sup> hard coated polycarbonate allows the beauty of your engine to shine through while blocking the heat. N5200 Heat Deflector fits 2009

FLHT/FLHTC/FLHTCU Electra Glide.