



ROUNDED CONTOUR-PROFILE

PREVENTION

- Use water and neutral soap to clean the windshield.
- Check the tightening of the fasteners periodically.
- Park the scooter facing the sun, avoiding the sun-reflection effect that may damage some parts.
- Park if possible on even surfaces.

Thanks for your attention.

ID.	DESCRIPTION	QTY.
1	Clear windshield	1
2	Metal support 70x80°xØ8	2
3	5,5x14 screw to tight into plastic	2
4	Plastic washer	4
5	5,5x16 screw to tight into plastic	2
6	Support with drill through	2
7	Screw with drill through	2
8	Special washer	2
9	Ø10x230 bar	2
10	M8 nut cover	4
11	M8/125x25 left fastener (left side)	1
12	M8/125x25 (right side)	1
13	M8 washer DIN 125/A	2
14	M8/125 nut DIN 6923	2
15	Bellow drill cover	2
16	Plastic support	2
17	M8 lock nut left fastener	1
18	Arrowhead Ø8xØ14x6	2
19	M8 nut cover	2
20	Screw cap	4
21	M8/125 DIN 915 lock nut	1
22	Ø8 nylon washer	4

