


UNIVERSAL RISERS



3672P	M8x55 + M8x65 screws	4+4
3740P	M8x45 + M8x55 screws	4+4
3741P	M8x55 + M8x65 screws	4+4

 $NOTE_1$: To verify the screws, add the elevator height to the original screw (20 or 30) $NOTE_2$: When mounting the 30mm lift it is very possible that the wiring of the motorcycle is short, so it must be replaced.

When it comes to <u>quality motorcycle handlebars & controls</u>, <u>Puig is the brand you can depend on</u>.