


## WINDSHIELD MOUNTING INSTRUCTIONS

Ref.: 5267W

ID.	DESCRIPTION	QTY.
I	Windshield	1
2	M5 DIN982 Inox nut	4
3	M5x13 phillips screw	4
4	M5x20 DIN912 Inox screw	4
5	Ball bearing bridle	2
6	Medium-spacer Ø22mm	2
7	Medium-spacer Ø26mm	2
8	M6x50 DIN912 Inox screw	2
9	M6 DIN982 Inox nut	2
10	Rod guide	2
П	Handlebar bridle Ø29mm	2
12	Barrette Inox	2
13	Rod with ball bearing	2
14	Exterior cap	2
15	Bar cover	2
16	Trim	I







It would be convinient to re-tight the windshield screws, specially the ones that are fi xed to the motorcycle, whenever you maintain the vehicle.

Thanks for your attention.

## WINDSHIELD MOUNTING INSTRUCTIONS TOURING TRAVELLER II

Ref.: 5267W

