

ROUNDED CONTOUR-PROFILE


PREVENTION

- Use water and neutral soap to clean the windshield.
- Check the tightening of the fasteners periodically.
- Park the scooter facing the sun, avoiding the sun-reflection effect that may damage some parts.
- Park if possible on even surfaces.

Thanks for your attention.

ID.	DESCRIPTION	QTY.
1	Clear windshield	1
2	Metal support 20x5x64x73°	2
3	Plastic support	2
4	Plastic washer	4
5	5,5x14 screw to tight into plastic	2
6	Support with drill through	2
7	Screw with drill through	2
8	Special washer	2
9	Ø10x210 bar	2
10	M8 nut cover	6
11	M8/125x50 screw DIN 931 (right side)	2
12	M8/125x50 left fastener (left side)	1
13	Ø8 washer DIN 125/A	2
14	Ø14xØ8x30 arrowhead	2
15	M8 lock nut (right side)	2
16	Below drill cover	2
17	5,5x12 screw to tight into plastic	2
18	M8 DIN915 nut left fastener (left side)	1
19	Ø8 nylon washer	4
20	M8 DIN6923 nut	2

WINDSHIELD ADAPTABLE TO
PIAGGIO LIBERTY 50/S - 125/S
 Mod.: TS
 Ref.: 5850W





Puig puts everything within reach.

Check out the collection of motorcycle windshields & fairings we offer.