





ROUNDED CONTOUR-PROFILE

PREVENTION

Use water and neutral soap to clean the windshield.
Check the tightening of the fasteners peridiocally.
Park the scooter facing the sun, avoiding the sunreflection effect that may damage some parts.
Park if possible on even surfaces.
Thanks for your attention.

| D. | DESCRIPTION | QTY |
|----|--------------------------------------|-----|
| 1 | Clear windshield | 1 |
| 2 | Metal support Ø8 70-80° | 2 |
| 3 | 5,5x12 screw to tight into plastic | 2 |
| 4 | Plastic washer | 4 |
| 5 | 5,5x14 screw to tight into plastic | 2 |
| 6 | Support with drill through | 2 |
| 7 | Screw with drill through | 2 |
| 8 | Special washer | 2 |
| 9 | Ø10x210 bar | 2 |
| 10 | M8/125x20 screw, left fastener | 2 |
| 11 | M8 washer | 2 |
| 12 | M8/125 nut cover DIN 6923 | 2 |
| 13 | Bellow drill cover | 2 |
| 14 | Plastic support | 2 |
| 15 | OEM mirror extension (original part) | 2 |
| 16 | M8 nut cover | 6 |
| 17 | M8/125 lock nut, left fastener | 2 |
| 18 | Ø8 nylon washer | 4 |

WINDSHIELD ADAPTABLE TO HONDA VISION 50/110 11'-





