

## Racing Screens







## PREVENTION

- •Use water and neutral soap to clean the windshield.
- Check the tightening of the fasteners peridiocally.
- Park the scooter facing the sun, avoiding the sunreflection effect that may damage some parts.
- Park if possible on even surfaces.


Thanks for your attention.

## ROUNDED CONTOUR-PROFILE

ID.	DESCRIPTION	Q.
1	Clear windshield	
2	Metal support 70x80°x∅8	1
3	Regulator (adjusts the inclination of the windshield)	
4	Plastic washer	
5	5,5x14 screw to tight into plastic	
6	Support with drill through	
7	Ø10,5x42 screw with drill through	
8	Special washer	
9	Ø10x210 bar	
10	M8 nut cover	
11	M8x25 screw	
12	5,5x12 screw to tight into plastic	
13	M8 washer DIN 125/A	
14	Arrowhead Ø8xØ20x6	
15	Arrowhead Ø8xØ14x12	
16	Plastic support	
17	M8 nut cover DIN 6923	
18	M8x35 screw DIN 931	
19	Platen (width adjuster for windshield bracket)	
20	Bellow drill cover	
21	Screw cap	
22	Adapter hex. thread ext.left M8 to thread int.M8	
23	Adapter hex. thread ext.M10 to thread int.M8	
24	Adapter hex. thread ext.left M10 to thread int.M8	
25	Adapter hex. thread int.left M8 to thread ext.M8	:
26	Adapter hex. thread int.M10 to thread ext.M8	
<del>p²for</del>	- Adapter hex. thread int left M10 to thread ext.M8 - Quality Puig products on our website.	

## WINDSHIELD ADAPTABLE TO UNIVERSAL

Mod.: **TS** Ref.: **6371** 



Buy quality motorcycle windshields  $\&\ fairings\ in\ our\ online\ store.$